New Mexico Occupational Health & Safety

FATAL FACTS



No. 8775-030

Accident Type:	Carrabt baturasa	
Accident Type:	Caught between	
Number of Fatalities	1	
Weather Conditions:	Dry, Calm, Warm	
Type of Operation:	Ramp Maintenance	
Size of Work Crew:	1	
Competent Safety Monitor on Site:	No	
Safety and Health Program in Effect:	Yes	
Was the Worksite Inspected Regularly:	No	
Training and Education Provided:	Yes	
Employees Job Titles:	Mechanic	The second secon
Age & Gender:	Male, 52	
Experience at this Type of Work:	Years	
Time on Project:	1 day	

BRIEF DESCRIPTION OF ACCIDENT

A belt loader became stuck in an inoperable position. A mechanic used a second belt loader to lift the ramp of the first loader so he could examine the lift. While attempting to repair the broken loader, movement occurred and the inoperable ramp descended upon the mechanic causing fatal injuries.

INSPECTION RESULTS

The investigation resulted in the issuance of two serious citations. The first citation was for not performing periodic inspection of energy control procedures -29 CFR 1910.147(c)(6)(i). The second serious citation was for not following proper lockout/tagout procedures as described in 29 CFR 1910.147(d).

ACCIDENT PREVENTION RECOMMENDATIONS

The recommendations made by OHSB were to provide more frequent training for lockout/tagout procedures.